- 05102 18 MA	Y 1965 } S E	C R Z Z	Dite	1 70 Fra	tel
	For the second s	Reference 、 メルール (See Mark - See Configuration Action	13 DEA		<ul><li>*** ** *** *** *** *** *** *** *** ***</li></ul>
<ul> <li>And the state of t</li></ul>	on The large of the property of the control of the	eth englandig yezhoù sakhour rauskabenkake zonek eo bret er da akhouriske Rausk y capital sek plockasjaken e ethologiak o da ethologiaken e ek trouget sak	5 Idea	- 113	il. 7 mas trascate desperatores
; DIRECTOR			16 00	warrens and figure a description of the second	en et le presentation de la company de la co
ð ;	25X1A	•	18 13	D. COSTONIA POR SERVICE STATE OF THE SERVICE STATE STA	gra fi d sidjeni jajšinojosinama materija. Pri ki sidjeni jajšinojosinama materija.
·····································		e e e e e e e e e e e e e e e e e e e		RIORITY	
	18 MAY 1965		Harris and an arminum	IN S	17693
	18 MAY 1965	034 1-15	Estation assessment	IN: 8	n II a mekada tanggan dan hal Manggan dan panggan dan kanggan
TOR: 0605Z	A 21 september of the 1935 for the content of the property of	054 1-15	Established States of the Contract of the Cont		n a sepande a september des

- 1. LACK OF SUFFICIENT ADVANCE INFORMATION THAT (285C) WAS IN
  70MM FORMAT USING DELTA II (1128) CAMERA CONFIGURATION OCCASIONED
  CERTAIN PROCESSING PROBLEMS:
- A. WE HAD NOT WORKED TYPE 8430 AT 70MM IN OUR PROCESSORS PREVIOUSLY. WE ENCOUNTERED CERTAIN CHEMISTRY PROBLEMS BECAUSE THE ESTABLISHED FORMULAR WERE NOT PROPER AND REQUIRED CONSIDERABLE MODIFICATION.
- B. INDIVIDUAL FRAMES HAD NO DATA CHAMBER OR NUMBERING SEQUENCE WHICH COULD BE ANALYZED HERE. AS A RESULT WE HAD TO ARBITRARILY NUMBER THE DUPE POS IN CHRONOLOGICAL ORDER BEFORE WE COULD EFFECT OUR ROUTE SEARCH. (NOTE: IF EDITING DUE TO HOST OR FRIENDLY COUNTRY COVERAGE WERE SUBSEQUENTLY DETERMINED NECESSARY, RENUMBERING WOULD HAVE BEEN REQUIRED.)
  - C. IT WAS IMPOSSIBLE TO FOLLOW THE TITLING INSTRUCTIONS REVELVED

DB

GEOUD 1

SECRET

<u>25X1A</u>		
	0379	(IN87693)

PAGE --2--

BECAUSE OF THE LARGE NUMBER OF CHARACTERS REQUIRED A SINGLE TITLING HEAD ON THE DUAL HEAD BLAKETRON WOULD NOT HOLD ALL CHARACTERS IN 12 POINT TYPE.

- D. TWO OF OUR RECENTLY RECEIVED BLAKETRON TITLERS HAD TO BE DRILLED AND TAPPED TO ACCEPT THE TWO ADDITIONAL 70 MM CONVERTER ROLLERS. THEY HAD COME FROM MANUFACTURER SET UP FOR 9 1/2 INCH ONLY AND HAD ONLY ONE 70MM ROLLER WHICH DID NOT PERMIT ACCURATE TRACKING.
- E. ONE CLEANER WAXER CONSTANTTY PRESENTED TRACKING PROBLEMS
  DUE TO POOR DESIGN CHARACTERISTICS OF 70MM CONVERSION SPINDLE.
- 2. FOR BUDGETARY AND SUPPLY PURPOSES REQUEST WE BE ADVISED IF
  IT IS PLANNED TO UTILIZE THE 70MM FORMAT FREQUENTLY IN FUTURE MISSIONS.
  WILL THE 9 1/2 INCH FORMAT BE PHASED OUT AND IF SO, WHEN? CONTINUED
  USE OF 70MM WILL ALSO HAVE A SIGNIFICANT IMPACT ON OUR PROGRAM TO
  ACQUIRE PHOTO INTERPRETATION READ-OUT EQUIPMENT AND RECTIFICATION
  TRANSFORMATION DEVICES.
- J. NO TRACKER FILM RECEIVED WITH THIS MISSION. CAN WE ASSUME THAT NORMALLY WE WILL NOT RECEIVE TRACKER?

END OF MESSAGE